Firmware Chart

Revision 10.30.26

Product	Serial Number	Current Version	File Name	Current Version (DSP)	File Name (DSP)
Seeker+		1.01			
Bolt		1.80	BLT180.BIN		
Tensor		1.80	TEN176.BIN		
Seeker		1.80	SEK177.BIN		
Vision		5.60	VIS560.BIN		
Revolution		5.97	REV597.BIN		
Guardian		4.50	HKS450.BIN		
Guardian	> 25000	1.46	GRD146.BIN		
Guardian	> 29049	1.80	GRD177.BIN		
Cell Guardian	> 20000	2.17	TRZ217.BIN		
Eagle – 220, 330, 440 (Serial)		4.43	EGL443.BIN		
Eagle – 220, 330, 440 (USB)		4.50	HKE450.BIN		
Eagle 120		4.50	HK120450.BIN		
Eclipse		5.07			
LDU		1.02	LDU102.BIN		
ViP+	< 61000	1.57	VIP157.BIN	1.23	DSP123.BIN
ViP+ ***	> 61070	2.36	VIPB236.BIN	2.09	DSPB209.BIN
iVS-3 / 600P	> 61070	2.36	VIPB236.BIN	2.09	DSPB209.BIN
iVS-3 Rev 2	> 61070	2.36	VIPB236.BIN	2.09	DSPB209.BIN
SVM-10		2.36	VIPB236.BIN	2.09	DSPB209.BIN
VP-2		2.33	VP2233.BIN		
iVS-2SX *		2.33	VS2SX233.BIN		
iVS-2SX Plus		3.20	VS3SX320.BIN		
iVS-3S **		3.20	VS3SX320.BIN		
iVS-1S		1.16	VSS116.BIN		
iVS-3		2.44		Not field upgradable	
iVS-3 / 600E		2.44		Not field upgradable	
VP-1		1.24		Not field upgradable	
VS-3		2.44		Not field upgradable	

**If your iVS-2S firmware is 2.27 or lower, call PMI Support*

*** If your iVS-3S firmware is 2.20 or lower, call PMI Support*

**** If your ViP™ serial number is between 61000 and 61070, call PMI Support*

Power Monitors, Inc.
800 N Main St, Mt Crawford, VA 22841 • (800) 296-4120 • www.powermonitors.com