

# Firmware Chart

Revision 3.13.25



Product	Serial Number	Current Version	File Name	Current Version (DSP)
Bolt		1.72	BLT172.BIN	
Tensor		1.72	TEN172.BIN	
Seeker		1.72	SEK172.BIN	
Vision		5.60	VIS560.BIN	
Revolution		5.96	REV596.BIN	
Guardian		4.50	HKS450.BIN	
Guardian	> 25000	1.46	GRD146.BIN	
Guardian	> 29049	1.72	GRD172.BIN	
Cell Guardian	> 20000	2.17	TRZ217.BIN	
Eagle – 220, 330, 440 (Serial)		4.43	EGL443.BIN	
Eagle – 220, 330, 440 (USB)		4.50	HKE450.BIN	
Eagle 120		4.50	HK120450.BIN	
Eclipse		5.07		
LDU		1.02	LDU102.BIN	
ViP+	< 61000	1.57	VIP157.BIN	1.23
ViP+ ***	> 61070	2.36	VIPB236.BIN	2.09
iVS-3 / 600P	> 61070	2.36	VIPB236.BIN	2.09
iVS-3 Rev 2	> 61070	2.36	VIPB236.BIN	2.09
SVM-10		2.36	VIPB236.BIN	2.09
VP-2		2.33	VP2233.BIN	
iVS-2SX *		2.33	VS2SX233.BIN	
iVS-2SX Plus		3.20	VS3SX320.BIN	
iVS-3S **		3.20	VS3SX320.BIN	
iVS-1S		1.16	VSS116.BIN	
iVS-3		2.44		Not field upgradable
iVS-3 / 600E		2.44		Not field upgradable
VP-1		1.24		Not field upgradable
VS-3		2.44		Not field upgradable

\* If your iVS-2S firmware is 2.27 or lower, call PMI Support

\*\* If your iVS-3S firmware is 2.20 or lower, call PMI Support

\*\*\* If your ViP™ serial number is between 61000 and 61070, call PMI Support

Power Monitors, Inc.

800 N. Main St. Mt. Crawford, VA 22841 · (800)296-4120 · [www.powermonitors.com](http://www.powermonitors.com)