

Firmware Chart

Revision 1.7.26



Product	Serial Number	Current Version	File Name	Current Version (DSP)	File Name (DSP)
Bolt		1.80	BLT180.BIN		
Tensor		1.77	TEN176.BIN		
Seeker		1.77	SEK177.BIN		
Vision		5.60	VIS560.BIN		
Revolution		5.97	REV597.BIN		
Guardian		4.50	HKS450.BIN		
Guardian	> 25000	1.46	GRD146.BIN		
Guardian	> 29049	1.77	GRD177.BIN		
Cell Guardian	> 20000	2.17	TRZ217.BIN		
Eagle – 220, 330, 440 (Serial)		4.43	EGL443.BIN		
Eagle – 220, 330, 440 (USB)		4.50	HKE450.BIN		
Eagle 120		4.50	HK120450.BIN		
Eclipse		5.07			
LDU		1.02	LDU102.BIN		
ViP+	< 61000	1.57	VIP157.BIN	1.23	DSP123.BIN
ViP+ ***	> 61070	2.36	VIPB236.BIN	2.09	DSPB209.BIN
iVS-3 / 600P	> 61070	2.36	VIPB236.BIN	2.09	DSPB209.BIN
iVS-3 Rev 2	> 61070	2.36	VIPB236.BIN	2.09	DSPB209.BIN
SVM-10		2.36	VIPB236.BIN	2.09	DSPB209.BIN
VP-2		2.33	VP2233.BIN		
iVS-2SX *		2.33	VS2SX233.BIN		
iVS-2SX Plus		3.20	VS3SX320.BIN		
iVS-3S **		3.20	VS3SX320.BIN		
iVS-1S		1.16	VSS116.BIN		
iVS-3		2.44		Not field upgradable	
iVS-3 / 600E		2.44		Not field upgradable	
VP-1		1.24		Not field upgradable	
VS-3		2.44		Not field upgradable	

* If your iVS-2S firmware is 2.27 or lower, call PMI Support

** If your iVS-3S firmware is 2.20 or lower, call PMI Support

*** If your ViP™ serial number is between 61000 and 61070, call PMI Support

Power Monitors, Inc.

800 N. Main St. Mt. Crawford, VA 22841 · (800)296-4120 · www.powermonitors.com